



Process Measurement & Controls, Inc

11 Old Sugar Hollow Road, Danbury, CT 06810 U.S.A

Tel. (203) 792-8686 Fax. (203) 743-2051

Website: www.pmc1.com Email: sales@pmc1.com



Installation Instructions for MP-11 Moisture Protection Reference Volume

The PMC MP-11 is used to provide gauge pressure sensors with an ambient reference with no moisture/humidity that can cause errors and/or sensor failure. Once connected to the reference tube of a pressure sensor the MP-11 allows for a change in barometric pressure with very little error. The advantage of the MP-11 is zero maintenance. There are no filters or desiccant to check or change.

